

## कार्यकारी अभियंता यांचे कार्यालय,

सोलापूर ( सा.बां.) विभाग, सोलापूर  
सात रस्ता, कारीगर पेट्रोल पंपासमोर  
सोलापूर ४१३००३.

Phone No. (०२१७) २३१२३१०	E-mail :- solapur.ee@mahapwd.com
जा.क्र./एसओएल / पीडब्ल्युडी / रेशा / ४२४६ / सन-२०१८.	दिनांक :- ०९ / ०७ / २०१८.


प्रति,  
प्राचार्य,  
माईर्स, विश्वशांती गुरुकुल स्कूल,  
केगांव, सोलापूर.

विषय :- इमारत सुस्थितीत असल्याबाबतचे प्रमाणपत्र मिळणेबाबत..

संदर्भ :- १) आपले पत्र जा.क्र. MIT /SOL/२०१८-१९/०३७२/२०१८ दि.२८/०५/२०१८.  
२) उपविभागीय अभियंता, सा.बां.उपविभाग, उत्तर सोलापूर यांचे पत्र जा.क्र.आस्थापना/११३०/२०१८  
दि - ०५/०७/२०१८.

उपरोक्त संदर्भिय विषयान्वये, प्राचार्य, माईर्स विश्वशांती गुरुकुल स्कूल केगांव, सोलापूर यांनी इमारत सुस्थितीत असल्याबाबतचे प्रमाणपत्र मिळणेबाबत संदर्भ क्र.१ अन्वये अर्ज सादर केला. त्याप्रमाणे सदर अर्जदाराचे जागेवर जाऊन उपविभागीय अभियंता, सा.बां.उपविभाग, उत्तर सोलापूर यांनी पाहणी केली आहे व त्याबाबतचा अहवाल संदर्भ क्र. २ चे पत्रान्वये या कार्यालयास सादर केलेला आहे. त्यांनी सादर केलेल्या अहवालावरून क्र. A, B, B-२ या तीन इमारतीची पाहणी केली असून पाहणीच्या वेळी इमारतीचे बांधकाम सर्व दृष्टीकोनातून पूर्ण झालेले होते. त्यामुळे इमारतीचा पाया त्यांचे कॉलम, विम, स्लॉब, इमारतीच्या इतर अंगाची व आर.सी.सी.डिझाईन ची माहिती उपलब्ध होऊ शकली नाही. परंतु इमारतीच्या बाहय भौतिक तपासणी केली असता, सदरच्या इमारती सुस्थितीत असल्याचे दिसते. हे आपल्या माहितीसाठी व पुढील कार्यवाहीसाठी.

कार्यकारी अभियंता,  
सार्वजनिक बांधकाम विभाग, सोलापूर  
प्रत :- उपविभागीय अभियंता, सार्वजनिक बांधकाम उपविभाग, उत्तर सोलापूर यांना माहितीसाठी रवाना.



PURANI  
MANISHKUMAR  
HEMANTKUMAR  
Digitally signed by  
PURANI MANISHKUMAR  
HEMANTKUMAR  
Date: 2023.07.28  
11:06:22 +05'30'

CHATE  
SWATI  
MUKUNDRAJ  
Digitally signed  
by CHATE SWATI  
MUKUNDRAJ  
Date: 2023.07.28  
11:07:23 +05'30'

**|| Marathi to English Translation of Building Safety Certificate ||**

**Office of the Executive Engineer**

Solapur (P.W.) Department, Solapur  
Seven Road, Opp. To Kargil Petrol Pump,  
Solapur – 413003

Phone No. (0217) 2312310	Email :- solapur.ee@mahapwd.com
O.W. No./SOL/PWD/RS/4246/Year-2018	Date :- 09/07/2017

To,  
**Principal**  
MAEER's Vishwashanti Gurukul School  
Kegaon, Solapur,

**Subject : Regarding Building Safety Certificate**

Reference :- 1) Your Letter O. W. No. MIT/SOL/2018-19/0372/2018 Dated 28/05/2018  
2) Letter by Dy. Divisional Engineer, P.W. Sub Division, North Solapur  
O.W. No. Establishment/1130/2018 dated 05/07/2018

With the reference to the above subject, MAEER's Vishwashanti Gurukul School, Kegaon, Solapur has submitted an application to receive Building Safety Certificate vide reference No. 1. Accordingly, Dy. Divisional Engineer, P.W. Sub Division, North Solapur has visited the Location and submitted a Report vide reference no. 2. As per the report submitted by them, A, B, B-2 these three buildings have inspected and the construction was completed in all respect at the time of inspection. Therefore, building base, their columns, Beam, Slabs, and other parts of building and Information regarding the RCC designs were not able to available, but on the external physical inspection of the buildings, the said buildings are appears to be in good condition.

This is for your information and further processing.

PURANI  
MANISHKUMAR  
HEMANTKUMAR

Digitally signed by  
PURANI MANISHKUMAR  
HEMANTKUMAR  
Date: 2023.07.28 11:06:41  
+05'30'

CHATE  
SWATI  
MUKUNDRAJ

Digitally signed by  
CHATE SWATI  
MUKUNDRAJ  
Date: 2023.07.28  
11:06:58 +05'30'

Sd/-  
**Executive Engineer**  
Public Works Department, Solapur

Copy to : Dy. Divisional Engineer, Public Works Sub Division, North Solapur



25 JUL 2023

ATTESTED

VANI VISHNU SHINTE  
NOTARY GOVT OF INDIA  
PUNE DISTRICT (MAHARASHTRA)  
Regd.No 11179  
EXP NC.5/4/2025